


Fig. 52








Fig. 53

| | | | | | | | | | | | | | | | | | | |
|----|-----------------------|------|--------|--------|-----------|------|------------|------------------------------|------------------|--------|-----------------|-----------|-----------|--------------------|-----------|--------------|-----|--------|
| S: | 2.1.10.3.4.5.6.7.8.9. | 11. | 12.12' | 13.13' | 14.15.16. | 18. | 19. | 20. | 22.23. | 24.25. | | | | | | | | |
| R: | 1.2. | 3.4. | 5. | 6. | 7. | 9.8. | 10. | 40.22.11.14.12.13.13'.15.16. | 17.18.19.20.22A. | 21. | 26.23.25.24.10' | 27.28.29. | 30.31.59. | 32.33.34.35.37.36. | 38.39.46. | | | |
| C: | 1. | 2.3. | 4.5. | 6. | 18.19.7. | 8.9. | 4.6.13.10. | 11. | 14.15. | 16. | 12.43.17. | 27 | 87. | 90. | 20. | 21.22.23.24. | 26. | 25.71' |

○ tensions en volts
 □ courants en mA
 ∞ valeur efficace
 sans indice : continu
 ou valeur moyenne



| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|----|-----------|-----|---------|-----------|--------------|--------------|-----------------|------------------|-----|-----------|--------------------|--------|--------|--------------|--------------------|------------------|--------|--------------------|--------------------------|------------------|-----------------|-----|-----------|--------------|-----------------|-----|-----------|--------------|--------|
| S: | 28.29.71. | 30. | 31.31a. | 32. | 33.34. | 26.72. | 36. | 37.39.40. | 38. | 42.43.44. | 45.46.47. | 48.49. | 51.52. | 54. | 55. | 58. | 60.61. | 62.63.64.66.67.69. | 70.71.72.96.73.95.97.74. | 80.75.80'.77.76. | 79. | 81. | 83.85.86. | 60.61. | 87.88.89.90.91. | 92. | 93.94.84. | 81.82.83.84. | 86.85. |
| R: | 41. | 43. | 44. | 45. | 48. | 50. | 99.31.98.53. | 54.56.53.57.100. | 60. | 62.63. | 64. | 66.67. | 69. | 70.71. | 72.96.73.95.97.74. | 80.75.80'.77.76. | 79. | 81. | 83.85.86. | 60.61. | 87.88.89.90.91. | 92. | 93.94.84. | 81.82.83.84. | 86.85. | | | | |
| C: | 28.29. | 30. | 32. | 33.34.35. | 36.37.91.39. | 40.41.42.38. | 67.92.93.74.45. | 48. | 47. | 49.50. | 55.51.60.52.51.54. | 56.57. | 58.68. | 59.67.88.62. | 66'.71. | 72. | 74.75. | 76. | 78.77. | 76. | 78.77. | 76. | 78.77. | 76. | 78.77. | 76. | 78.77. | 76. | 78.77. |



Brochage des tubes
 (vue de dessous
 sauf. L22-23-24)